



FUEL/WATER SEPARATOR SPIN-ONS

with Open Port for Bowl

BF1222-O



Contains: Port Thread: 3-12
Integral Post Seal

Fits: Ford Engines

Replaces: Ford F2TZ-9N-184-A;
Motorcraft FD3375

Thread: 1-14

O.D.: 4 1/4 (108.0)

Length: 4 1/8 (104.8)

F. Gskt.: [1] Included

I. Gskt.: [1] Included

BF1223-O



Contains: Port Thread: 3 3/4-10
Integral Post Seal

Fits: Ford Trucks

Replaces: Ford F1HZ-9365-A; Motorcraft FD3368

Thread: 1-14

O.D.: 4 1/4 (108.0)

Length: 5 7/32 (132.6)

F. Gskt.: [1] Included

I. Gskt.: [1] Included

Related To: BF1223 (Standard Version)
BF1223-SP (Sensor Port Version)

BF1249-O



Contains: Port Thread: 1 1/4-10
Integral Post Seal

Fits: Hamm Rollers; Optional on Cummins Engines

Replaces: Nissan FL6442N; Fleetguard FS1242

Thread: 1-14

O.D.: 3 21/32 (92.9)

Length: 6 5/8 (168.3)

F. Gskt.: [1] Included

I. Gskt.: [1] Included

O-Ring: [1] Included

Related To: BF1249 (Standard Version)
BF1249-SP (Sensor Port Version)

BF1281-O



Contains: Port Thread: M95 x 2.5
Integral Post Seal

Fits: Primary Fuel for Racor 4120 Series
Fuel/Water Separators

Replaces: Racor R120P

Thread: 1-14

O.D.: 4 9/32 (108.7)

Length: 11 5/16 (287.3)

F. Gskt.: [1] Included

Related To: BF1281 (Standard Version)

BF1283-O



Contains: Port Thread: M95 x 2.5
Integral Post Seal

Fits: Caterpillar Equipment, Industrial, Marine,
Truck Engines; Racor 4120 Series

Replaces: Caterpillar 129-0373; Racor R120S

Thread: 1-14

O.D.: 4 13/32 (111.9)

Length: 8 19/32 (218.3)

F. Gskt.: [1] Included

I. Gskt.: [1] Included

Related To: BF1283 (Standard Version)
BF1283-SP (Sensor Port Version)

BF1287-O



Contains: Port Thread: M85 x 2.5
Integral Post Seal

Fits: Komatsu Dump Trucks

Replaces: Komatsu 600-311-3210, 600-319-3240

Thread: 1 1/4-12

O.D.: 4 7/8 (123.8)

Length: 9 29/32 (251.6)

A. Gskt.: [1] Attached

F. Gskt.: [1] Included

I. Gskt.: [1] Included

BF1288-O



Contains: Port Thread: M95 x 2.5
Integral Post Seal

Fits: Komatsu Dump Trucks, Equipment

Replaces: Komatsu 600-311-4510, 600-319-4500

Thread: 1 1/4-12

O.D.: 4 7/8 (123.8)

Length: 9 29/32 (251.6)

F. Gskt.: [1] Included

I. Gskt.: [1] Included

BF1290-O



Contains: Port Thread: B80 x 3.0 8A Metric Buttress

Replaces: CLARCOR Filtration (China) WBF219B;
Foton Lovol 1307211500005

Thread: 1-14

O.D.: 4 11/32 (110.3)

Length: 6 13/32 (162.7)

I. Gskt.: [1] Included

O-Ring: [1] Included

BF1292-O



Contains: Port Thread: M95 x 2.5
Integral Post Seal

Fits: Deutz Engines; Deutz-Fahr, Fendt Tractors

Replaces: Deutz 4291642; Fendt F339202060120;
Iveco 42549295; Mercedes-Benz 4771602,
A0004771602; Racor R90T-D-MAX

Thread: 1-14

O.D.: 4 5/32 (105.6)

Length: 6 5/16 (160.3)

I. Gskt.: [1] Included

O-Ring: [1] Included

BF1294-O

Contains: Port Thread: 3 3/4-10 2B Buttress Integral Post Seal
Fits: Scania Genset Engines
Replaces: Scania 1518512; SF-Filter SK3360
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 7 5/32 (181.8)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1295-O

Contains: Port Thread: 3 3/4-10 2B Buttress
Replaces: CLARCOR Filtration (China) CX1010; DCD 4102H1520
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 5 1/32 (127.8)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1296-O

Contains: Port Thread: B80 x 3.0 8A Metric Buttress
Fits: Doosan Equipment
Replaces: CLARCOR Filtration (China) WBF219B1; Sinotruk 13050733
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 6 13/32 (162.7)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1297-O

Contains: Port Thread: B80 x 3.0 8A Metric Buttress
Replaces: CLARCOR Filtration (China) WBF219H; Weichai Power 612630080088
Thread: 1-14
O.D.: 4 9/32 (108.7)
Length: 9 3/32 (231.0)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1298-O

Contains: Port Thread: M95 x 2.5
Replaces: Foton Lovol 1105111500002; CAMC 1125A86D-010; CLARCOR Filtration (China) CX1014A
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 6 5/32 (156.4)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1299-O

Contains: Port Thread: 3 3/4-10 2B Buttress
Replaces: Yuchai Watyuan 612630080205
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 7 13/16 (198.4)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1329-O

Contains: Port Thread: 3 3/4-10 2B Buttress Integral Post Seal
Fits: Blue Bird Buses; Racor 690R Series Filter Systems; Freightliner, Oshkosh, Scania, Volvo Trucks
Replaces: DAF 1296851; Scania 1393640; Racor R90P; Volvo 8159975
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 6 5/16 (160.3)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1345-O

Contains: Port Thread: 3-12
Fits: International Engines, Trucks
Replaces: International 1618385-C91; Donaldson P550729
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 5 9/32 (134.1)
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1346-O

Contains: Port Thread: M95 x 2.5
Fits: Ford, Freightliner, International, Sterling, Western Star Trucks; Mercedes-Benz Engines; Racor Housings
Replaces: Racor S3226P; Donaldson P550554; Fleetguard FS19593
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 6 5/16 (160.3)
I. Gskt.: [1] Included
O-Ring: [1] Included
Related To: BF1346 (Standard Version)
 BF1346-SP (Sensor Port Version)

BF1348-O

Contains: Port Thread: M95 x 2.5
Fits: Blue Bird Buses; Freightliner, Hino, Peterbilt Trucks; Racor 325 Series
Replaces: Racor S3225P; Donaldson P550436; Fleetguard FS19521; Luber-finer LFF5849; Wix 33630
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 5 3/16 (131.8)
A. Gskt.: [1] Attached
I. Gskt.: [1] Included
O-Ring: [1] Included

BF1355-O

Contains: Port Thread: M95 x 2.5
Fits: Volvo VN Series, VN730, VNL300, VNL430, VNL730 Trucks
Replaces: Racor S3238P; Thermo King 11-9982; Volvo 85104856
Thread: 1 1/4-14
O.D.: 4 7/8 (123.8)
Length: 6 5/16 (160.3)
F. Gskt.: [1] Included
I. Gskt.: [1] Included
Grommets: [1] Included

BF1358-O

Contains: Port Thread: 3 3/4-10 Integral Post Seal
Fits: Volvo Dump Trucks, Equipment
Replaces: Volvo 11110474, 11110668
Thread: 1-14
O.D.: 4 13/32 (111.9)
Length: 8 19/32 (218.3)
F. Gskt.: [1] Included
I. Gskt.: [1] Included
Related To: BF1358-SP (Sensor Port Version)

BF1366-O

Contains: Port Thread: M80 x 2.5
Integral Post Seal

Fits: R.V.I., Volvo Trucks

Replaces: Volvo 20998367; Donaldson P559628; Fleetguard FS19735

Thread: 1-14

O.D.: 3 21/32 (92.9)

Length: 5 5/8 (142.9)

I. Gskt.: [1] Included

O-Ring: [1] Included

BF1383-O

Contains: Port Thread: B80 x 3.0 8A Metric Buttress

Fits: DAF Engines, Trucks; Doosan, Terex Equipment

Replaces: M.A.N. 51.12501.7288, 51.12503.0052; Daewoo K1006529; CLARCOR Filtration (China) WBF219

Thread: 1-14

O.D.: 4 9/32 (108.7)

Length: 9 3/32 (231.0)

I. Gskt.: [1] Included

O-Ring: [1] Included

BF1386-O

Contains: Port Thread: M80 x 2.5
Integral Post Seal

Fits: Mack, Volvo Engines, Trucks

Replaces: Mack 21017305; Volvo 20879806

Thread: 1-14

O.D.: 4 1/4 (108.0)

Length: 5 3/16 (131.8)

I. Gskt.: [1] Included

O-Ring: [1] Included

BF1387-O

Contains: Port Thread: M80 x 2.5
Integral Post Seal

Fits: Volvo Engines, Trucks

Replaces: Volvo 20879812

Thread: 1-14

O.D.: 4 11/32 (157.2)

Length: 6 5/16 (160.3)

I. Gskt.: [1] Included

O-Ring: [1] Included

BF1388-O

Contains: Port Thread: M95 x 2.5
Integral Post Seal

Fits: R.V.I., Volvo Trucks

Replaces: R.V.I. 7420851191; Volvo 20853583; Racor R60T-D-MAX

Thread: 1-14

O.D.: 4 1/4 (108.0)

Length: 5 1/8 (130.2)

I. Gskt.: [1] Included

O-Ring: [2] Included

BF1389-O

Contains: Port Thread: 3 3/4-10 2B Buttress
Integral Post Seal

Fits: Volvo Engines, Trucks

Replaces: Volvo 20381204; Racor R45T; Donaldson P550746; Fleetguard FS19734

Thread: 1-14

O.D.: 4 1/4 (108.0)

Length: 3 17/32 (89.7)

I. Gskt.: [1] Included

O-Ring: [1] Included

BF1390-O

Contains: Port Thread: 3 3/4-10 2B Buttress

Fits: Volvo Trucks

Replaces: Racor R90T; Volvo 20450423; Fleetguard FS19551

Thread: 1-14

O.D.: 4 11/32 (110.3)

Length: 6 3/16 (157.2)

I. Gskt.: [1] Included

O-Ring: [1] Included

BF1391-O

Contains: Port Thread: M95 x 2.5

Fits: Mercedes-Benz Engines, Trucks

Replaces: Mercedes-Benz 4771302, A0004771302; Fleetguard FS19914

Thread: 1-14

O.D.: 4 1/4 (108.0)

Length: 8 21/32 (219.9)

I. Gskt.: [1] Included

O-Ring: [1] Included

Related To: BF1359-SP (Sensor Port Version)

BF1395-O

Contains: Port Thread: M95 x 2.5

Fits: Freightliner Cascadia with Detroit Diesel Series 60 Engine

Replaces: Alliance ABPN122R50421; Donaldson P551075; Fleetguard FS1071

Thread: 1-14

O.D.: 4 13/32 (111.9)

Length: 8 19/32 (218.3)

F. Gskt.: [1] Included

I. Gskt.: [2] Included

BF1398-O

Notes: Inside-Out Flow Direction

Contains: Port Thread: M80 x 2.5
Integral Post Seal

Fits: Volvo Trucks with D6B Engine

Replaces: Volvo 20386080; Racor R25P; Fleetguard FS19704

Thread: 1-14

O.D.: 3 21/32 (92.9)

Length: 5 5/8 (142.9)

O-Ring: [1] Included

BF9866-O

Contains: Port Thread: M95 x 2.5

Fits: John Deere Equipment

Replaces: John Deere RE532952, RE539465

Thread: 7/8-14

O.D.: 4 3/8 (111.1)

Length: 8 11/16 (220.7)

F. Gskt.: [1] Included

I. Gskt.: [1] Included

BF9867-O

Contains: Port Thread: M95 x 2.5

Fits: Evobus Citaro Buses; Mercedes-Benz, Renault Trucks

Replaces: Bomag 05825015; Renault 7420754418; Racor R160TDMAX; Donaldson P551033

Thread: 1-14

O.D.: 4 13/32 (111.9)

Length: 8 21/32 (219.9)

F. Gskt.: [1] Included

I. Gskt.: [1] Included

BF9871-O

Contains: Port Thread: 3 3/4-10 2B Buttress
Fits: Freightliner, Sterling, Western Star Trucks
Replaces: Alliance ABPN/122R-50418; Fleetguard FS19593
Thread: 1-14
O.D.: 4 5/16 (109.5)
Length: 6 5/16 (160.3)
F. Gskt.: [1] Included
I. Gskt.: [1] Included

BF9898-O

Contains: Port Thread: M95 x 2.5
Fits: Freightliner Cascadia, FLD, Business Class M2 Trucks
Replaces: Alliance ABPN122BR90FRT10; Freightliner BR90FRT10, RAIBR90FRT10; Donaldson P551066
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 6 5/16 (160.3)
F. Gskt.: [1] Included
I. Gskt.: [1] Included
Grommets: [1] Included

BF9912-O

Contains: Port Thread: 3 3/4-10 Buttress
Replaces: Atlas Copco 2914809200; Fleetguard FS19775
Thread: 1-14
O.D.: 4 1/4 (108.0)
Length: 3 15/32 (88.1)
F. Gskt.: [1] Included
I. Gskt.: [1] Included

QUICK CROSS-REFERENCE

BALDWIN	DONALDSON	FLEETGUARD	HENGST	LUBER-FINER	MANN & HUMMEL	RACOR	BALDWIN	DONALDSON	FLEETGUARD	HENGST	LUBER-FINER	MANN & HUMMEL	RACOR
BF1222-O	P553375	FS1281	-	LFF5824B	-	R42	BF1348-O	P550436	FS19521	-	LFF5849	-	S3225P
BF1223-O	P550730	FS1287	-	LFF8063	-	R60T	BF1355-O	-	FS19799	-	-	-	S3238P
BF1249-O	P553201	FS1242	-	-	-	-	BF1538-O	-	FS19753	H7121WK10	LFF9753	WK1176X	-
BF1281-O	P551077	FS19754	-	-	-	R120P	BF1366-O	P559628	FS19735	H700WK	LFF3293	WK94033X	R260P
BF1283-O	-	-	-	-	-	-	BF1383-O	P550778	FS19769	H710WK	LFF9769	PL420X	-
BF1287-O	-	-	-	-	-	-	BF1386-O	P550913	FS19918	-	LFF3358	WK10006Z	-
BF1288-O	P550937	-	-	LFF5357	-	-	BF1387-O	-	FS19920	H7091WK30 D199	-	-	-
BF1290-O	-	-	-	-	-	-	BF1388-O	-	FS19895	H7063WK30	-	WK10401X	R60T-D-MAX
BF1292-O	-	FS19950	H7091WK10	-	WK1070X	R90T-D-MAX	BF1389-O	P550746	FS19734	-	-	WK1020X	R45T
BF1294-O	-	-	-	-	-	-	BF1390-O	P550747	FS19551	H7090WK10	-	WK10605X	R90T
BF1295-O	-	-	-	-	-	-	BF1391-O	-	FS19914	H701WK	-	WK10807X	R160T
BF1296-O	-	FS19907	H304WK	-	PL270X	-	BF1395-O	P551075	FS1071	-	LFF8707U	-	R50421
BF1297-O	-	-	-	-	-	-	BF1398-O	-	FS19704	H7025WK30	-	WK94032X	R25P
BF1298-O	-	-	-	-	-	-	BF9866-O	-	-	-	-	-	-
BF1299-O	-	-	-	-	-	-	BF9867-O	P551033	FS19949	-	-	WK10806X	R160T-D-MAX
BF1329-O	P550747	FS19532	H7090WK30	LFF8038	WK10603X	R90P	BF9871-O	P559112	-	-	LFF8957	-	-
BF1345-O	P550729	FS19547	-	LFF3579	-	R43	BF9898-O	P550747	FS19593	-	LFF5849	-	-
BF1346-O	P550554	FS19593	-	LFF5850	-	S3226P	BF9912-O	-	FS19775	H7045WK30	-	-	R45P