



# Baldwin - Spin-on Fuel Filters | #BF9903-SP



## **Local Contact**

#### **Parker Sales Company UK**

Tachbrook Park Drive

Tachbrook Park

Warwick

**United Kingdom** 

CV34 6TU

### **Phone**

+44 (0)1926 317878

## Get your Parker account Today!

Create one account to manage everything you do with Parker, from your shopping preferences to your application access.

Register now

Modern fuel injection systems require fuel be free of both particulate and water contamination. Baldwin spin-on fuel

♦ Share / Email

## **Technical Specifications**

## **Product Type:**

Fuel/Water Separator Spin-on with Drain and Sensor Port

Notes:

CAUTION: Furnished O-Ring must be installed on Post for Seal

**Contains:** 

Standpipe; Sensor Port Thread: 9/16-18

**Thread Size:** 

1-14

**Outside Diameter:** 

4 1/4 (108.0)

Length:

9 7/32 (234.2)

Includes:

I. Gasket: [1] Included; O-Ring: [2] Included

Micron Rating:

10 Absolute

**Compatible Competitor Part Number:** 

Caterpillar 3261641; Fleetguard FS19968

Application:

Caterpillar Equipment; Kenworth, Western Star Trucks

Brand:

Baldwin

Industry:

Automotive

Heavy-duty on-highway transportation

Commercial trucks and buses

Agriculture

Construction

Industrial

Marine

Mining

Oil & Gas

**Power Generation** 

#### **Product Style:**

**Fuel Filter** 

## **Technology:**

Filtration

## **Item Information**

"Modern fuel injection systems require fuel be free of both particulate and water contamination. Baldwin spin-on fuel filters with heavy-duty construction keep fuel clean and engines running at maximum efficiency. New fuel systems

operate at higher pressures (up to 60,000 psi) and tighter tolerances than ever before. Microscopic particles in the fuel, as small as 2-3 microns, can cause abrasive wear severely damaging the fuel injection system and other high pressure engine components. Baldwin Filters offers more than 1100 different fuel filters, fuel managers, coalescers, and fuel/water separators to protect your engine.
- Show Less
CAD Drawings + Files

No CAD files available